# 5.3 EXISTING SITE CONDITIONS SANTIAGO 7-8 CHARTER MIDDLE



## **EXISTING SITE INFORMATION**

Year Built: 1973 Year Modernized: N/A Student Population (2019-2020): 984 Grade Levels: 7-8 Number of Permanent Classrooms: 34 Number of Relocatables: 6 Site Acreage: 23.10 Permanent Building Area: 76,034 sf Relocatable Classroom Area: 6,240 sf Other Relocatable Area: 960 sf

Parking: 89 spaces + 2 accessible

## **OVERVIEW**

The Condition Assessment information outlined on the following pages was gathered in the following four ways:

- 1. Each Principal filled out a survey related to the current educational programs, the needs and goals of those programs, and the ways in which physical space is supporting or hindering the program goals.
- 2. The District provided a Facilities Assessment that was completed internally in 2018.
- 3. LPA met with and interviewed the various trades in the Maintenance & Operations Department to understand what work has

# Orange Unified School District Facilities Master Plan



been completed, where they have identified issues and what items generate the most work orders.

4. LPA team members met with each Principal to ask questions and walk each site with them to get a better understanding of the layout, areas of concern, and work completed to-date.

# RECENT DEFERRED/MAJOR MAINTENANCE & RENOVATION PROJECTS

- 2012 HVAC Upgrades/Energy Conservation Project
- 2013 Fire Alarm and Site Utilities (H2O & Gas) Upgrades
- 2019 Solar panels installed over parking and amphitheater
- 2019 New exterior paint throughout

#### PRINCIPAL COMMENTS

Site

- The hardcourts need to be resurfaced.
- There are ADA sloping issues towards the playfields.
- Both parking lots and black top in PE area have cracks. Asphalt needs slurry seal coat and restriping.
- Asphalt adjacent to room 702 needs replacing due to root damage.
- Retaining Wall Retaining wall at back of school needs repair.
- Atrium Floor is uneven and needs repair.
- Irrigation system is in poor condition and needs major repairs/replacement.
- Concrete area behind kitchen needs repair especially the drainage area.
- Concrete behind Room 703 needs repair.



Building

- Restrooms need modernization.
- There is a large Special Education population; toileting currently happens at the nurse's station.
- Would like to have large garage doors/ operable walls to expand the STEM classrooms outdoors (400 building).
- Student Restrooms: (100s, 200s, and PE) need renovation and upgrading.
- PE Lockers: Student lockers in PE building need replacing or major repair/refurbishing.
- Cafeteria Tables Tables are in poor condition and need replacement.
- Library Doors: Entry double doors and rear door are in poor condition and need replacement, cannot be repaired any further.
- Floor covering throughout is in need of replacement. Room 114 and choir room are especially bad.
- Snack area tables are old and in disrepair, need replacing.
- Storage Room Relocatable: Roof leaks and siding need repair.

#### Programs

- Interested in having a health clinic on campus (community wellness center).
- Current CTE pathways include culinary arts, wood shop, web/graphic design, and e-sports.

**Highest Priorities** 

- 1. Concrete floor in the atrium (between the main office and Library).
- 2. Completion of solar panel project in the amphitheater.
- 3. Removal of fence between the school and the surplus property to allow for additional parking. The property line is different than the fence line.

## **CONDITION ASSESSMENT**

Each category evaluated is ranked using a facilities condition category as follows:

- CATEGORY [0]: No Work.
- CATEGORY [1]: Minor Modernization.
- CATEGORY [2]: Standard Modernization.
- CATEGORY [3]: Major Modernization/ Reconfiguration/ Complete Replacement.

## **ASSESSMENT OF SITE**

#### **Curb Appeal**

Category [0]

#### Parking

Category [2]

• Additional parking is needed accommodate pick-up and drop-off.

#### Paving

Category [1]

#### **AC Paving**

Category [1]

#### **Ramps and Stairs**

Category [2]

• Access to the locker rooms is a concern.

#### SITE AMENITIES

Shade Shelter - Lunch Canopy Category [1]

### Lunch Tables and Benches

Category [3] • In need of replacement.

# Orange Unified School District Facilities Master Plan



#### Drinking Fountains Category [3]

Play Equipment Category [1]

#### Landscape

#### Category [2]

• Water pooling issues across playfields - in need of attention.

#### Irrigation

Category [3]

Fencing/Gates Category [1]

### **ASSESSMENT OF BUILDINGS**

#### EXTERIOR

to

Overall Rating: Category [2]

#### Exterior Finish/Paint

Category [0]

• Exterior painting received a refresh in Summer 2019

#### **Door & Frames**

Category [2]

Many doors and frames need to be replaced.

#### Windows

Category [2]Many windows need to be replaced.

#### Roof

Category [1]

Done in the last ten years.

ADA Compliance Category [3]



#### INTERIOR

Category [2] at both permanent and portable buildings.

- Carpets and VCT are old, worn, and stained throughout campus in need of attention.
- Ceiling tiles scuffed, damaged, and stained in many locations throughout campus - in need of attention.
- Classroom casework and fixtures in need of refresh or replacement.

#### RESTROOMS

ADA Compliance: [3]

• Restrooms in need of an upgrade.

## **ASSESSMENT OF SYSTEMS**

#### SITE UTILITIES

Overall Rating: Category [1]

#### MECHANICAL

Overall Rating: Category [1]

• Received modernization upgrades within the last 10 years.

#### PLUMBING

Overall Rating: Category [1]

• Received modernization upgrades within the last 10 years.

#### ELECTRICAL

Overall Rating: Category [0]

• Received modernization upgrades within the last 10 years.







## 5.3 EXISTING SITE CONDITIONS SANTIAGO 7-8 CHARTER MIDDLE

# Orange Unified School District Facilities Master Plan





Dense tree line causing safety hazard.



Locker room interior in need of attention.



Flooding issue on playfields.



Access/ramp concern to locker room.



Classroom casework due for an update.



In need of outdoor learning spaces.



Typical water fountains due for an update.



In need of proper IDF storage.



Playfields in need of attention.

## 5.3 EXISTING SITE CONDITIONS SANTIAGO 7-8 CHARTER MIDDLE

# Orange Unified School District





Central atrium area.



Typical portable classroom.



Home economics room.



ASB room.



Typical planting area.



Wood shop.



Drama classroom.



Lounge area.



Cafeteria/MPR.

# 5.3 EXISTING SITE CONDITIONS SANTIAGO 7-8 CHARTER MIDDLE

# Orange Unified School District Facilities Master Plan





Outdoor amphitheater.



SDC classroom.



Faculty lunch room.

Typical restroom.



Typical hallway.



Typical classroom.



Library.



Lecture hall.



Locker room.



Orange Unified School District Facilities Master Plan



	ΤΟΤΑ	L PROJECT COST (2021\$)
01. Modernize & Reconfigure Existing Classrooms	\$	3,131,000
02. Building Systems, Toilets & Improved Energy Efficiency	\$	595,000
03. Site Utilities	\$	-
04. Classroom New Construction	\$	-
05. Enrichment Programs & Electives	\$	4,026,000
06. Science Labs	\$	1,417,000
07. Assembly & Food Service Improvements	\$	2,391,000
08. Media Center	\$	1,174,000
09. Student Support / Counseling Services	\$	-
10. Administration & Staff Support	\$	1,388,000
11. Physical Education Improvements	\$	1,761,000
12. After School Support	\$	-
13. Safety & Security	\$	683,000
14. Campus Arrival: Parking, Drop-off & Entry Plaza	\$	120,000
15. Outdoor Learning Environments & Quads	\$	-
16. Exterior Play Spaces, Playfields & Hardcourts	\$	1,624,000
17. Flexible Furniture	\$	1,195,000
18. Technology Infrastructure & Equipment	\$	1,344,000
Total Project Cost (2021\$)	\$	20,849,000



240'

120' 60' 0




EXISTING ON OVERALL SITE **7-8 CHARTER MIDDLE** PLAN

5.3

Orange Unified School District Facilities Master Plan





N

0 30' 60' 1" = 120'

120'

## English History Resource Specialist Special Day Class Vacant Electives / Labs Science Lab Computer Lab Shared Spaces , Multi-Purpose Room Media Center Locker Room Admin / Faculty

Math

	FW FL WR O N PSY SPCH OT/PT CONF COUN PTA	Conference Ro	e Fherapy/Phy: Joom	
	CARES ASES S T U C	Oort Spaces Expanded Learn After School Ed Storage Toilet Utility Custodial Kitchen	ning Program	fety
		able Classro Entry	oom	
isti		9/20 Enrollme	ent: 1022	,
ac	hing S	tations:		
to th en	sh, ENG ry, HIST nce, SCI ives, EL puter La	-	6 5 6 12 0	

g 2019/20 Enrollment:	1022
ing Stations:	
, ENG	6
, HIST	5
	6
e, SCI	6
es, ELEC	12
iter Lab, COMP	0
	0
	5
2-Vacant)	2
Total:	42

EXISTING SI **7-8** 

5.3

B CHARTER MIDDLE

Orange Unified School District Facilities Master Plan



318



N

60' 120'

0

1" = 240'

240'



MODERNIZATION

 PLAN
 Orange Unified School District


 MIDDLE
 Facilities Master Plan

5.3

PROPOSED SANTIAGO

OVERALL SITE 7-8 CHARTER

319



## N 1" = 120'